

C92

Westchester County Department of Health
Division of Environmental Sanitation

P1029

41 21 39 734257 WELL COMPLETION REPORT

This report is to be completed by well driller and submitted to Health Department, together with laboratory report of analysis of water sample indicating water is of satisfactory bacterial quality, before certificate of construction compliance is issued.

Well construction to be in accordance with Bulletin SD-62
"RULES & REGULATIONS RELATING TO INDIVIDUAL WATER SUPPLIES"

770 H

LOCATION: MUNICIPALITY Town of Carmel SECTION 76 BLOCK 3 LOT 5
WELL OWNER: Pecchia Plumbing Cuppy Rd Mahopac N.Y.
Name Street Address City and Town
WELL DRILLER: J. Toelsh Sons Maple Ave Armonk N.Y.
Name Street Address City and Town

CASING DETAILS		YIELD TEST		WATER LEVEL		SCREEN DETAILS	
Length:	45 Feet	Bailed	or	(measure from land surface)			
		X Pumped	6 Hours	Static:	41 Feet	Make:	
Diameter:	6 Inches	Yield:	2 G.P.M.	When Bailed	or Pumped	300 Feet	Length Ft. Slot Size
Kind:	Steel					Diameter	In.

TOTAL DEPTH OF WELL 350 FEET

WELL LOG

Depth From Ground Surface	Give description of formations penetrated, such as: peat, silt, sand, gravel, clay, hardpan, shale, sandstone, granite, etc. Include size of gravel (diameter) and sand (fine, medium, coarse), color of material, structure (Loose, packed, cemented, soft, hard). For example: 0 ft. to 27 ft. fine, packed, yellow sand; 27 ft. to 134 ft. gray granite.
0 Ft. to 35 Ft.	HARD PAN BOULDER
35 Ft. to 220 Ft.	GRAY ROCK
220 Ft. to 270 Ft.	BLACK ROCK
270 Ft. to 350 Ft.	GRAY ROCK
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	
Ft. to Ft.	

Date Well Was Completed 5/16/76

Date of Report 12/10/76

Well Driller

Signature

James Toelsh